

INSTALLATION INSTRUCTIONS FOR JOINING SECTIONS WITH COUPLING SET (ERS-102)

Install terminal connectors to bus bars on one end (#1). Place bus bar sections end to end and loosen screws (#2) to clear openings in connectors. Slide bus bars into terminal connectors (#3), shifting the bus bars slightly if necessary, and retighten screws (#2). Up to 1/32" gap may be left in bus bar joint. **Caution:** Insure the connectors are centered in the casing.

Hook side plates (#4) into underside slots (#5) of casings and swing up into position. Insert screws (#6) into side plates and tighten so that the casings are clamped securely. Place insulator (#7) on connectors (#3). Mount cover (#8) on side plates with screws (#9).

